

50 Cotton/50 Poly T-Shirt.



HOW TO MEASURE



With arms down at sides, measure around the upper body, under arms and over the fullest part of the chest.

SIZE CHART

	S	М	L	XL	2XL	3XL	4XL	5XL
Chest	34-36	38-40	42-44	46-48	50-52	54-56	58-60	62-64

COLOR INFORMATION



PMS 5535 C

PRODUCT MEASUREMENTS

	S	м	L	XL	2XL	3XL	4XL	5XL
Chest	18	20	22	24	26	28	30	32
Sleeve Length	15 5/8	17	18 1/2	20	21 1/2	22 7/8	24 1/4	25 3/8
Body Length at Back	28	29	30	31	32	33	34	35

CHEST

Measured across the chest one inch below armhole when laid flat.

CHEST

SLEEVE LENGTH

Start at center of neck and measure down shoulder, down sleeve to hem.